




Quick Installation Guide

Wi-Fi Outdoor CPE

AirMax5X II









2. Login Web Configuration


Use a browser to access http://192.168.1.253, pop up the login page shown below,input the login password: admin, enter into the home page.

Login Web Interface






Setup Wizard



- ► Repeat mode

 Bridge the exist wireless signal then transmit Wi-Fi for more range
- ► AP mode
 In this mode, NAT, DHCP, firewall, and all WAN-related functions are turned off. All wireless and wired interfaces are bridged together, regardless of LAN and WAN

3.Bridge Status



Login CPE (work as repeater), will see signal strength, green is normal, between -70dBm to -40dBm.

www.airlive.com

Declaration of Conformity

We, Manufacturer/Importer

AirLive Technology Corporation 4F, No.132, Lane 235, Baoqian Rd., Xindian Dist., New Taipei City 23145, Taiwan

Declare that the product

Wi-Fi 5Ghz N300 Outdoor CPE

AirMax5X II

is in conformity with

In accordance with 2014/30/EU and 2014/35/EU Directive

Clause EN 55032:2015

Description

Electromagnetic compatibility (EMC)

■ EN 62368-1

Electromagnetic compatibility (LVD)

■ CE marking

((

Manufacturer/Importer

Name: A van Rossem Position/ Title: Product Manager Place: Republic of China (Taiwan) Date: June 2022

Regulatory Approvals

CE Statement

This product complies with the 2014/30/EU and 2014/35/EU directives, including the following safety and EMC standards:

■ EN 55032:2015

Electromagnetic compatibility (EMC)

■ ETSI EN 301 489-1 V2.2.3 (2019-11) Electromagnetic compatibility (EMC)

- ETSI EN 301 489-17 V3.2.4 (2020-09) Electromagnetic compatibility (EMC)
- EN 55035:2017

Electromagnetic compatibility (EMC)

■ EN 62368-1:2014+A11:2017 Electromagnetic compatibility (LVD) - Safety

- ETSI EN 302 502 V2.1.3 (2017-07)
- EN IEC 62311:2020
- EN 50665:2017

• CE Marking Warning

This is a Class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

Trouble Shooting

.Static electricity

2.Running time too long 3.Lightning stroke

Trouble Solution Reason 1.Use Wi-Fi analysis to choose the best channel, Distance is too long,or there are some or change to 5G CPE CPE should be in normal distance, and avoid bar 3.CPE's angle in wrong direction, weak signal 3.Adjust the angle of CPE according to signal strength .Press reset button in 10 seconds to reset device, the default password is admin Input wrong password 2.Re-input the password 3.Clear cookie,run arp -d to clear MAC table. 1.Ping 192.168.1.253 to see connection status 2.Stop other devices or change to another IP .Local IP is not in the same network segment 2.IP is taken by other devices 3.LAN Connection or Ethernet cable has problem 4.Too much cookie, MAC address haven't update 3. Check LAN Connection and Ethernet cable 4. Clear cookie, run arp -d to clear MAC address 2.Some problem in CPE's PoE port 2.Check if POE port of CPE is OK 3.Ethernet cable is loose, RJ45 port is wrong 3. Check if Ethernet cable is loose, if Ethernet cable input voltage of POE adapter is normal Packet Latency Ethernet cable circuit Network virus attack 1.Adjust the distance, angle and channel to decrease latency 2.Check if there is circuit in the network Check if port isolated to avoid network virus and broadcast storm Decrease the access users. 4.Too much access users

1.Make CPE or POE adapter need ground connection

Running time over 7 days, reboot it
 After lightning, device POE port broken or unstable, better to deploy lightning conductor .

Trouble Shooting







